

Inspection Photos
Location Name: Seventy Holes 44-5 PAD
Location ID: 433304



Photo 1 – Tank Battery



Photo 2 – Wellheads

Inspection Photos
Location Name: Seventy Holes 44-5 PAD
Location ID: 433304




Photo 3 – Stained Soil at Compressor



Photo 4 – Unmarked 2" Riser on the Northeast corner of location

Inspection Photos
Location Name: Seventy Holes 44-5 PAD
Location ID: 433304



Photo 5 – Wells 44-41-5HNB and T-P-5HNB missing Wellhead Signs




Photo 6 – Unused Methanol Tank/Pump west of Wellheads