

## Inspection Photos

Location Name: Hunter Canyon #12

Location ID: 312684

Inspection Date: November 18, 2019



Photo #1 – Aerial view of the location, the pit is located within the red oval.



Photo #2 – Location sign.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Hunter Canyon #12**  
**Location ID: 312684**  
**Inspection Date: November 18, 2019**



**Photo #3 – View of the pit looking northwest.**



**Photo #4 – View of the pit looking north.**





**Inspection Photos**  
**Location Name: Hunter Canyon #12**  
**Location ID: 312684**  
**Inspection Date: November 18, 2019**



**Photo #5 – View of the unmarked 1-inch riser.**



**Photo #6 – View of the sign on the 225 gallon methanol tank.**

