

Inspection Photos
Location Name: Seventy Holes P-4 PAD
Location ID: 433884



Photo 1 – P-T-4HNB Wellhead



Photo 2 – Stained Soil at Compressor



Inspection Photos
Location Name: Seventy Holes P-4 PAD
Location ID: 433884




Photo 3 – Stained Soil at Compressor




Photo 4 – Unmarked Risers East of Compressor



Inspection Photos
Location Name: Seventy Holes P-4 PAD
Location ID: 433884



Photo 5 – Properly treat or dispose of oily waste in accordance with 907.e. Wildlife Netting is in disrepair. Please replace.



Photo 6 – Unmarked Risers North of Tanks

Inspection Photos
Location Name: Seventy Holes P-4 PAD
Location ID: 433884



Photo 7 – Unused Secondary Containment