

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 1 – Wellheads



Photo 2 – Tank Battery

Inspection Photos
Location Name: State Seventy Holes 21-6 PAD
Location ID: 438056



Photo 3 – Stained Soil at Compressor



Photo 4 – Unmarked Riser north of Compressor