

Inspection Photos
Location Name: Pad 8
Location ID: 333033



Photo 1: Wellhead Sign



Photo 2: Wellhead (equipment removed)

Inspection Photos
Location Name: Pad 8
Location ID: 333033



Photo 3: Wellhead Sign



Photo 4: Wellhead (equipment removed)

Inspection Photos
Location Name: Pad 8
Location ID: 333033



Photo 5: Wellhead Sign



Photo 6: Wellhead (equipment removed)

Inspection Photos
Location Name: Pad 8
Location ID: 333033



Photo 7: Wellhead Sign



Photo 8: Wellhead (equipment removed)



Inspection Photos
Location Name: Pad 8
Location ID: 333033



Photo 9: Tank Battery Sign



Photo 10: Tank Battery; appears water hose is removed
(snow covering area)

Inspection Photos
Location Name: Pad 8
Location ID: 333033



Photo 11: No NFPA placard/BBLs faded



Photo 12: BBLs faded

Inspection Photos
Location Name: Pad 8
Location ID: 333033




Photo 13: BBLs faded on crude oil tank.



Photo 14: Appears stained soil is removed (snow covering area)

Inspection Photos
Location Name: Pad 8
Location ID: 333033



Photo 15: Appears stained soil is removed (snow is covering area)



Photo 16: Appears debris has been removed (snow covering area)

Inspection Photos
Location Name: Pad 8
Location ID: 333033



Photo 17: Appears trash is removed (snow covering area)



Photo 18: Trash south of tank battery