

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2019

Submitted Date:

12/02/2019

Document Number:

696101626**FIELD INSPECTION FORM**Loc ID 306584 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289855	WELL	PR	05/01/2019	OW	123-24950	SHOEMAKER A 12-8	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Active.

Centralized Battery serves 4 Location IDs (306587, 306584, 306585, 306586).
(Well(s): 2: Producing | PR ; 1: Shut-In | SI ; 1: Temporarily Abandoned | TA).
(3: Other wells associated w/ Location ID #306586 are connected to another Battery/Facility).

Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type:	#		

Comment:	Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 0				
Comment:	Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.				
Corrective Action:				Date:	
Type: Gas Meter Run	# 0				
Comment:	Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.				
Corrective Action:				Date:	
Type: Emission Control Device	# 0				
Comment:	Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.				
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.501549,-104.491986
Comment:	Centralized Battery serves 4 Location IDs (306587, 306584, 306585, 306586). Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				
Comment:	Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment:				Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.		
Corrective Action:				Date:		
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities										
Facility ID:	289855	Type:	WELL	API Number:	123-24950	Status:	PR	Insp. Status:	SI	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS				
Comment:		<div>Shut-In SI. Observed production valves shut.</div>								
Corrective Action:		<div></div>						Date:		<div></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 12/02/2019 at approximately 12:31 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SHOEMAKER A-66N64W /12SENE Location ID: 306584 Well Name: Shoemaker A 12-8 API: 05-123-24950 Location County: Weld County, Colorado Weather: Clear w/ partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Active.</p> <p>Centralized Battery serves 4 Location IDs (306587, 306584, 306585, 306586). (Well(s): 2: Producing PR ; 1: Shut-In SI ; 1: Temporarily Abandoned TA). (3: Other wells associated w/ Location ID #306586 are connected to another Battery/Facility).</p> <p>Refer to Field Inspection Report Doc. #696101622 and/or Location ID #306587 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/02/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101627	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5002471