

Inspection Photos

Location Name: Shoemaker /AA07-65HN Multi

Location #: 306586



Colorado Oil & Gas Conservation Commission
40.49908, -104.49076, 1413.0m, 243°
12/02/2019 11:55:29 AM

Photo #1

Shoemaker A 12-9 (05-123-24952) Wellsite

Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
40.50171, -104.49202, 1420.0m, 219°
12/02/2019 01:48:22 PM

Photo #2

Shoemaker A 12-7, 12-8, 12-9, 12-17 Battery

Active