

Inspection Photos

API: 05-061-06088

Operator: CHEMCO INC

Inspection Date: 11/25/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06088 | Date: 11/25/2019

Inspection Photos



Photo 1. Facing northwest toward the well site. The cement pad, risers, and wire have been removed. The well sign is posted and a fence is installed to protect wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06088 | Date: 11/25/2019