

Inspection Photos

Location Name: COCKROFT USX A-66N64W /11SENE

Location #: 333034



Photo #1

Cockroft USX A 11-8 Wellsite

Temporarily Abandoned | TA

Unused Equipment

prior insp.



Photo #2

Cockroft USX A 11-8 (05-123-24711) Wellsite

Temporarily Abandoned | TA

Unused Equipment: Appears removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COCKROFT USX A-66N64W /11SENE

Location #: 333034



Photo #3

Cockroft USX A 11-8 Battery site

Abandoned: ALL equipment removed

Reclamation progressing

prior insp.