


**Inspection Photos**  
**Location Name: Pronghorn 11-14-12HZ**  
**Location ID: 427785**



**Photo 1 – Pumping Unit**



**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: Pronghorn 11-14-12HZ**  
**Location ID: 427785**



**Photo 3 – Unmarked Risers at Pipe Rack**