

Inspection Photos

Loc#334457

Operator: CPX

Inspection Number: 692401342

Inspection Date: 8/21/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

August 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: CPX TPR Loc#334457



Photo#2:
Cuttings were in process of being spread on cut slope .

Photo#3:
Canada thistle (Noxious Weed).

August 21, 2019



Photo#4:
Undermining of root systems is occurring.



Photo#5:
Area of concern in Photo#4 indicated by arrow.

August 21, 2019



Photo#6:
Reservoir at base of Fill Slope. .



Photo#7:
Materials stockpile.

August 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: CPX TPR Loc#334457



Photo#8:
Debris, stored supplies.



Photo#9:
Debris, stored supplies.

August 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: CPX TPR Loc#334457