

# Inspection Photos

ID: 150396

Operator: CHEMCO INC

Inspection Date: 11/25/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

ID: 150396 | Date: 11/25/2019

## Inspection Photos



**Photo 1.** Facing east toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019

## Inspection Photos



**Photo 2.** The berm around the tanks have been built up however, soils are loose and not compacted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019



## Inspection Photos



**Photo 3.** There is oil stained soil on the road surface near the tank battery has not been cleaned up. Approximately 4 ft. x 4 ft. area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019

## Inspection Photos



**Photo 4.** Facing west toward the tank battery. Sign is posted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019



## Inspection Photos



**Photo 5.** There is a pile of soil material which contains oily soil stored near the tank battery. This soil waste pile must be removed and properly disposed of.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019



## Inspection Photos



**Photo 6.** The pipe risers are now protected by a metal fence. The left riser in the photo has LO/TO. The right does not.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019



## Inspection Photos



**Photo 7.** Facing northeast at the south side of the location. This pipe riser has no LO/TO.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019



## Inspection Photos



**Photo 8.** Facing northeast toward the location. The burnt debris in this area was removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019

## Inspection Photos



**Photo 9.** There is various unused equipment such as pipe being stored at the location. The corrective action to remove unused equipment has not been completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019



## Inspection Photos



**Photo 10.** There is various unused equipment being stored at the location. There are barrels and containers with no labeling. The corrective action to remove unused equipment has not been completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 11/25/2019