

RG 31-8-38
API: 05-103-10622
Inspection: 679706381



Photo 1. Location.

RG 31-8-38
API: 05-103-10622
Inspection: 679706381




Photo 2. Well head.



RG 31-8-38
API: 05-103-10622
Inspection: 679706381



Photo 3. Separator.

