


RG 12-4-398
API: 05-103-10758
Inspection: 679706383



39.82018, -108.40465, 6553.9ft, 350°
12/02/2019 02:23:28 PM

Photo 1. Location.

RG 12-4-398
API: 05-103-10758
Inspection: 679706383



Photo 2. Separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources