

Inspection Photos

Loc#324752

Operator: Sandridge

Inspection Number: 692401604

Inspection Date: 11/6/19






Photo#1:
View of BMP installed as Stormwater Conveyance to retention pond.

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Vaneta Loc#324752



Photo#2:
View of upgraded road & BMPs along road.



Photo#3:
View of upgraded road & BMPs along road

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Vaneta Loc#324752



Photo#4:
Area where further upgrade, installation of BMPs is needed at entry into site.

Photo#5:
Area where further upgrade, installation of BMPs is needed at entry into site

November 6, 2019



Photo#6:
Area where further upgrade, installation of BMPs is needed.



Photo#7:
Area where further upgrade, installation of BMPs is needed.

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Vaneta Loc#324752



Photo#8:

View of Reclamation area where traffic has been excluded and debris removed.

November 6, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Vaneta Loc#324752