

Inspection Photos

Location Name: GOLDEN EAGLE 28-7X

API#: 05-071-08732

INSP. #: 695101844



Colorado Oil & Gas Conservation Commission
37.13433, -104.85768, 328°
2019/12/03 12:26:59



Colorado Oil & Gas Conservation Commission
37.14665, -104.89031, 2233.0m, 317°
2019/12/03 12:28:03

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: GOLDEN EAGLE 28-7X

API#: 05-071-08732

INSP. #: 695101844



PHOTO 3: GUY LINE ANCHOR MARKER DOWN. INSTALL GUY LINE ANCHOR MARKER IN ACCORDANCE WITH RULE 1003.a. CA DATE 01-3-20.



PHOTO 4: TWO UNMARKED UNUSED RISERS NEAR X WELLHEAD. REMOVE UNUSED RISER IN ACCORDANCE WITH NTO AND RULE 603.f. CA DATE 02-3-20.

Inspection Photos

Location Name: GOLDEN EAGLE 28-7X

API#: 05-071-08732

INSP. #: 695101844



PHOTO 5: OILY IMPACTED SOIL INSIDE SOUND WALLS FOR COMPRESSOR ON ORIGINAL WELL. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 01-03-20

PHOTO 6: OILY IMPACTED SOIL NEAR X WELLHEAD. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 01-03-20

Inspection Photos

Location Name: GOLDEN EAGLE 28-7X

API#: 05-071-08732

INSP. #: 695101844



PHOTO 7: OILY IMPACTED SOIL OUTSIDE SOUND WALLS FOR ENGINE SKID FOR X WELL. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 01-03-20

PHOTO 8: OILY IMPACTED SOIL INSIDE SOUND WALLS OF X WELL UNDER ENGINE SKID. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 01-03-20