

Inspection Photos

Location Name: COCKROFT USX A-66N64W /11NWNE

Location #: 306461



Photo #1

Cockroft USX A 11-2 (05-123-24709) Wellsite

Temporarily Abandoned | TA

Weeds emerging – Consider mitigation

prior insp.



Photo #2

Cockroft USX A 11-2 Wellsite

Temporarily Abandoned | TA

Weeds NOW appear mitigated

Inspection Photos

Location Name: COCKROFT USX A-66N64W /11NWNE

Location #: 306461



Photo #3

Cockroft USX A 11-2 Battery Site

Abandoned – MOST equipment removed

Reclamation progressing

**Unused Equipment: Gas meter run / riser
prior insp.**



Photo #4

Cockroft USX A 11-2 Battery Site

Abandoned – MOST equipment removed

Reclamation progressing

**Unused Equipment: Gas meter run / riser
NOW removed**