



ADO OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT


NOTICE OF UNSATISFACTORY INSPECTION  
 NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100



API No. 05- <i>075</i> - <i>8870</i>		LEASE NAME: <i>Towing #1</i>	
LOCATION: <i>NE NE 29-9N-53W</i>		OPERATOR: <i>Donnelly</i>	
DATE: <i>5-20-96</i>		INSPECTOR: EBB \ Ed Binkley (970) 842-4465	
Insp. Type: <i>SR</i>	Insp. Status: <i>PA</i>	PA: <input checked="" type="checkbox"/> N	Pass/Fail: <input checked="" type="checkbox"/> F
		Viol.: Y <input checked="" type="checkbox"/> N	NOV: Y <input checked="" type="checkbox"/> N

INSPECTION ITEM (RULE)	COMMENTS	INPUT
Well ID Signs (210)		
Pits (Reserve/Production)(904)		
Fences (604 C.(3), 1003 A.)		
Tank Battery Equipment(604)		
Fire Walls/Berms/Dikes(604)		
General Housekeeping (603g)		
Spills(Oil/Water)(907)		
Bradenhead (207)		
Drilling /Workover (315)		
Surface Rehabilitation (317)	<i>marker for pipe line in</i>	
Miscellaneous	<i>grass field.</i>	



**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:



This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission. Submit a copy or FAX to the inspector with date remedied and your signature. EBB fax is 970-842-4467.