

Inspection Photos
Location Name: Strong 2-8
Location ID: 332565



Colorado Oil and Gas Conservation Commission
40.38076, -104.75945, 1446.5m, 281°
Dec 4, 2019 11:15:09

Photo 1: Tank Battery Signs



Colorado Oil and Gas Conservation Commission
40.38072, -104.75936, 1439.3m, 302°
Dec 4, 2019 11:16:48

Photo 2: Tank Battery; berm repaired

Inspection Photos
Location Name: Strong 2-8
Location ID: 332565



Photo 3: Labeling visible to roadside (east tanks)



Photo 4: Labeling visible to road side (west tank)

Inspection Photos
Location Name: Strong 2-8
Location ID: 332565



Photo 5: Leak repaired and cleaned up