

Inspection Photos

API#081-07167

Operator: North Shore Exploration

Inspection Number: 692401610

Inspection Date: 11/7/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to East.

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Shore Ex PA Martin livestock API#081-07167



Photo#2:
Area bare of Vegetation.



Photo#3:
Area bare of Vegetation.

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Shore Ex PA Martin livestock API#081-07167



Photo#4:
Graveled area at entry & down Location signs.



Photo#5:
Close ups of gravel remaining on Location.

November 7, 2019



Photo#6:
View down access road into Location.



Photo#7:
View out of Location, up access road.

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Shore Ex PA Martin livestock API#081-07167



Photo#8:
Unknown Riser, 50ft. East off road 99N; South of point where access road diverts & runs Southeast to Location.



Photo#9:
Arrow indicates position of riser on aerial view of Location.

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Shore Ex PA Martin livestock API#081-07167