

Grand Mesa Operating CO, Dado 1-21
073-06772

Inspection #688306419

12/02/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Well survey post

Colorado Oil and Gas Conservation Commission
39.42733, -103.55018, 5370.7ft, 37°
12/04/2019 10:01:34 AM



At NW cor of
location looking SE.

Colorado Oil and Gas Conservation Commission
39.42813, -103.55019, 5364.2ft, 141°
12/04/2019 10:03:14 AM



Looking SE

Colorado Oil and Gas Conservation Commission
39.42813, -103.5502, 5354.3ft, 170°
12/04/2019 10:03:18 AM



Colorado Oil and Gas Conservation Commission

39.42813, -103.5502, 5357.6ft, 201

12/04/2019 10:03:22 AM



Looking SW

Colorado Oil and Gas Conservation Commission
39.4272, -103.54935, 5400.3ft, 283°
12/04/2019 10:08:33 AM



At top of hill looking N

Colorado Oil and Gas Conservation Commission
39.42664, -103.55041, 5393.7ft, 358°
12/04/2019 10:11:11 AM