

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2019

Submitted Date:

12/04/2019

Document Number:

688306419

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection ☐
 469320 Sherman, Susan 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 35080

Name of Operator: GRAND MESA OPERATING CO

Address: 1700 N. WATERFRONT PKWY BL 600

City: WICHITA State: KS Zip: 67206

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Reilly, Pat	316-265-3000	preilly@gmocks.com	Designated Agent
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent
Housey, Melissa		melissa.housey@state.co.us	
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
469321	WELL	XX	11/20/2019		073-06772	DADO 1-21	XX

General Comment:Preconstruction Inspection

Construction contractor asked if the location could be looked at prior to beginning construction because of it being in a swale (see attached photos). Inspector contacted COGCC's OGLA Supervisor to see if the location could be moved or what needed to be done. COGCC's OGLA Supervisor said that he would talk with the COGCC's OGLA for that location. The Inspector would call back after going to location. Inspector verified GPS of stake with GPS on Form 2A. The swale is in a dry land crop field (winter wheat) with the well stake being on the hill to the west side of the swale. Contractor and Inspector talked with COGCC's OGLA while they were on location and it was decided by the OGLA that the location did not need to be moved as long as BMPs were placed to prevent sediment transport to the Arikaree. Moving the location approximately 50' to the west would put it over the top of the hill and into the next drainage. It would have required much more footage to move the location east and out of the bottom of the swale. Contractor will install surface roughening, compacted berms, and a dike on top of the side of the location that the swale is on and the OGLA agreed.

Inspected FacilitiesFacility ID: 469321 Type: WELL API Number: 073-06772 Status: XX Insp. Status: XX**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306420	Grand Mesa Dado 1-21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5005238