



Final Reclamation Inspection Form

Site: MELNYCHENKO 1
 Date: 6/20/2018 Inspector: Hank Raizen
 Conditions: 70 sunny

Land Use:: Crop Access Road in Use: No
 If Crop: Fallow If yes, in use by: _____
 If other land use: _____ Located on active pad? No
 Located in interim rec of active pad? No

TB inspected: No TB status: Location Unknown
 TB name and/or #: _____

	Present (Y/N)	Notes
Debris or Trash on Site	No	
Equipment on Site (culverts, pipes, etc.)	No	
Livestock Grazing/Disturbances	No	
Vehicle Disturbances	No	
Wildlife Disturbances	No	
Seed Germination	No	
Plants Vigorous	No	
Uniform growth (height and density)	No	
Undesirable Species (non-noxious weeds)	No	
Noxious Weeds	No	
Stormwater Issues (erosion)	No	
Subsidence (depressions, sinking)	No	
Site Re-contoured Properly	Yes	
Road Re-contoured Properly	Yes	
Road base/gravel on site (road or pad)	No	
Compaction (On-Site)	NA	6 in @ 300 psi
Compaction (Off-Site)	NA	6 in @ 300 psi
Reclamation area fenced	No	

Plants Observed	On Site	Off Site	Desirable
			NA

Recommendations:	
Seeding	No
Weed Control	No
Erosion Control	No
Compaction Alleviation	No
Other:	

Other Comments/Observations: No obvious issues. Reinspect when crops are growing to confirm lack of growth impacts.

Recommended for Final Form 4? No



PHOTOGRAPHIC LOG



Photograph 1: North facing photograph.



Photograph 2: East facing photograph.



Photograph 3: South facing photograph.



Photograph 4: West facing photograph.

PHOTOGRAPHIC LOG



Photograph 5: Overview photograph.

