

Inspection Photos
Location Name: Dietrich C 06-23
Location ID: 306117



Colorado Oil and Gas Conservation Commission
40.33789, -104.58876, 4747.5ft, 23°
12/05/2019 07:58:22 AM

Photo #1 No Trash on North side of location. On 12/5/19

Inspection Photos
Location Name: Dietrich C 06-23
Location ID: 306117



Photo #2 Trash on North side of location. On 11/12/19

Photo #3 Trash on North side of location. On 9/4/19