

Inspection Photos
Location Name: Lang USX AB /35-03 (Multi)
Location #: 422547



Photo #1

Lang USX AB 35-03 (05-123-33303) Wellsite

Shut-In | SI



Photo #2


Lang USX AB 35-19D (05-123-33308) Wellsite

Shut-In | SI

Inspection Photos

Location Name: Lang USX AB /35-03 (Multi)

Location #: 422547



Colorado Oil & Gas Conservation Commission
40.53516, -104.51979, 1452.0m, 273°
12/04/2019 02:36:23 PM

Photo #3

Lang USX AB 35-05D (05-123-33309) Wellsite

Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.5369, -104.51992, 1468.0m, 107°
12/04/2019 03:07:14 PM

Photo #4

Lang USX AB 35-03, 35-19D, 35-05D, 35-6 Battery site

Shut-down | Inactive