

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2019

Submitted Date:

12/05/2019

Document Number:

696101658

FIELD INSPECTION FORMLoc ID 306370 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288208	WELL	SI	08/01/2019	OW	123-24546	LANG-USX AB 35-6	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (422547, 306370).
(Well(s): 4: Shut-In | SI).

Refer to Field Inspection Report doc. #696101656 and/or Location ID #422547
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696101656 and/or Location ID #422547 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696101656 and/or Location ID #422547 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type:	#		

Comment:	Refer to Field Inspection Report doc. #696101656 and/or Location ID #422547 for Battery / Facility, Equipment info.				
Corrective Action:				Date:	
Type: Plunger Lift		# 1			
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.536698,-104.519742
Comment:	Centralized Battery serves 2 Location IDs (422547, 306370). Refer to Field Inspection Report doc. #696101656 and/or Location ID #422547 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288208	Type:	WELL	API Number:	123-24546	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>Shut-In SI. Observed production valves shut. COGCC records indicate last production: 07/2019. Locked-Out, Tagged Out LOTO.</div>							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 12/04/2019 at approximately 14:52 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: LANG-USX AB-67N64W /35SENW Location ID: 306370 Well Name: Lang-USX AB 35-6 API: 05-123-24546 Location County: Weld County, Colorado Weather: Clear w/ partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (422547, 306370). (Well(s): 4: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696101656 and/or Location ID #422547 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/05/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101659	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5005824