

Inspected Facilities

Facility ID: 277929 Type: WELL API Number: 071-08398 Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSPECTION DOC#687902005, CA WAS INVALID ASS THE OPERATOR HAD BEEN GIVEN A CA TO PERFORM AN MIT PIOR TO THE NEXT MIT DUE DATE AND THE INSPECTION WAS PERFORMED SEVERAL MONTHS BEFORE THAT DUE DATE.	beardsit	12/05/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101867	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5006302