

Inspection Photos
Location Name: GOLDEN EAGLE 21-10
API#: 05-071-08417
INSP. #: 695101850



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos

Location Name: GOLDEN EAGLE 21-10

API#: 05-071-08417

INSP. #: 695101850



PHOTO 3: UNUSED UNMARKED RISER NEAR ENGINE SKID.
REMOVE UNUSED RISER IN ACCORDANCE WITH NTO AND
RULE 603.f. CA DATE 2-3-20