

# *Inspection Photos*

*API#081-06413*

*Operator: HRM Resources*

*Inspection Number: 692401612*

*Inspection Date: 11/7/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Overviews of Location to North & South at Well GPS Position on North side of Lease road.

November 7, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: HRM Res PA FLB API#081-06413





Photo#2:  
View West over portion of Location on South side of  
Lease road & Unknown Riser.



Photo#3:  
Unknown Riser.

November 7, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: HRM Res PA FLB API#081-06413



**Photo#4:**  
View North over portion of Location on South side of Lease road & Unknown Riser.



**Photo#5:**  
Close up of Unknown Risers on site.

November 7, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: HRM Res PA FLB API#081-06413





Photo#6:

Close up of vegetation on North side of Lease Road which appears well established , though heavily grazed.

November 7, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: HRM Res PA FLB API#081-06413