

# Inspection Photos

API: 05-043-40027

Operator: CINNAMON CREEK OIL & GAS INC

Inspection Date: 12/4/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-043-40027 | Date: 12/4/2019

## Inspection Photos



**Photo 1.** Facing southwest along the access road. There is vehicle rutting and erosion along the access road toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40027 | Date: 12/4/2019



## Inspection Photos



**Photo 2.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40027 | Date: 12/4/2019