

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT



1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

☒ NOTICE OF UNSATISFACTORY INSPECTION

☐ NOTICE OF SATISFACTORY INSPECTION

API No. 05- 075 - 6274

LEASE NAME: Carey B-1

LOCATION: SWSE 29-9N-53

OPERATOR: Hoss

DATE: 1-16-96

INSPECTOR: Binkley 8424465

Insp. Type: Pr

Insp. Status: Pr

PA: Y

N

Pass/Fail: P ☒ F

Viol.: ☒ Y N

NOV: Y

☒ N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210)	Update name on sign	
Pits (Reserve/Production) (Rule 902, 903, 904)	20' covered skin Large pits 60x100 x (3)	
Fences (Rule 604.C.(3), 1003.A)	na	
Tank Battery Equipment (Rule 604)	2-300, VT	
Fire Walls/Berms/Dikes (Rule 604)	fair	
General Housekeeping (Rule 603.G)	weeds on site	
Spills (Oil/Water) (Rule 908)	slight oil in corner of 1st pit -	
Bradenhead (Rule 207)	pump	
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED:

Remove weeds from skin site
and remove oil from evaporation pit #1

Date Corrective Action Required By: 2-28-96

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

Notify Ed when work is done - 970 8424465