

WELL SITE INSPECTION FORM



00264399

Well Name CAREY B #1 API Number 05 -
Operator CHEVRON ROBERT L. HOSS Permit #
Location SWSE29-9N-53W County LOGAN
Field MT. HOPE Inspector R. Van Sickle
AL/PA/DA Inspection Results: Well Status:
Pass(Y) Fail(N) Date FN FD WO PR ✓ SI

Date of Inspection Before/During Drilling

Surf. Csg. Size Setting Depth Cmt. Vol. WOC time
Consistent with APD casing Program? YES NO Returns
Rig BOP'S Contact

Date of Inspection Before/During/After Completion 4-18-90

Prod. Csg. Set? ✓ Completion Rig/Activity
Drilling Pits: Closed ✓ Open Wellhead Installed Y N
Tank ID: Yes ✓ No N/A Skim Tank/Pit: Prod. Tanks: (2) 300 BBLs
Equipment VERT FU-HT Meter Run: Yes No ✓
Bradenhead Press: Fluid: No Yes Type Well Cat. 3A

AL/PA/DA Inspection

Date Plugged: Date Permit Expired:
Hole Plugged: Yes No Pits Backfilled: Yes No
Material Buried: Yes No N/A Site Clean: Yes No
Bond Release OK: Yes No Fed Hole Marker: Yes No

Date of Safety/Status Inspection

Comments: HUGE PITS! DUCKS USING PITS FOR SWIMMING. WATER
BEING DISCHARGED INTO DRAW WHICH RUNS INTO A STOCK
POND & BEYOND.

P.O. Box 22479
DENVER CO 80222

Violations: Yes ✓ No Notice Sent: Yes ✓ No Date Sent: 5-23-90