



PCE

LEASE INSPECTION FORM

Operator Self Date May 30 1985
Lease Name & No. Carey Unit Field Midvale East
Tank Battery No. 9N53029 County Logan
Location SWSE 29-9N-53W
Legal Description
Type of Inspection Reg Pit
Water Inflow _____ (Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)
Type of Tank

SKIM TANK _____

Pit No. 1 Skin 12x15 - Wire Cased - 100% - 2' Free

Pit No. 2 30x30 - Clear - 2' Free

Pit No. 3 30x50 - Clear - 3' Free

ADDITIONAL PITS 20x70 - Empty

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

RECOMMENDED ACTION (If Required) _____

INSPECTOR D. B. Becknell