

Inspection Photos

Pit Facility 113016

Well 107-06173

Remediation 14494

Inspection Date: 12/3/2019

Photos taken by Kris Neidel



Photo #1 location of excavation relative to existing gas line and AGT's.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Pit Facility 113016

Well 107-06173

Remediation 14494

Inspection Date: 12/3/2019

Photos taken by Kris Neidel



Photo #2 soil was removed with backhoe. Sample was collected into jars and a plastic bag from the hoe bucket.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Pit Facility 113016
Well 107-06173
Remediation 14494
Inspection Date: 12/3/2019
Photos taken by Kris Neidel



Photo #3 note grey sand, evidence of pit. Encountered at 8 feet below the surface.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Pit Facility 113016

Well 107-06173

Remediation 14494

Inspection Date: 12/3/2019

Photos taken by Kris Neidel



Photo #4 looking straight down into excavation. Sample was collected from the bottom of the 10' excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources