

WELL CATEGORY : 3 -



WELL SITE INSPECTION FORM

LOCATION 11NENW 6-9N-52W
OPERATOR Quest Oil Co.
WELL NAME Richerson #2

FIELD Padroni West
COUNTY Logan
PERMIT # _____

DATE OF INSPECTION DURING DRILLING: _____

RIG _____ SURFACE CASING: _____ DEPTH: _____
BOP'S _____ RETURNS: _____ WOC: _____
CONTACT _____ CMT VOL: _____
ADEQUATE AQUIFER PROTECTION? _____
COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: YES _____ NO _____ PRODUCTION STRING: _____
WATER DISPOSAL: PITS _____, INJECTED _____, COMMERCIAL _____, UNKNOWN _____, N.A. _____
PITS: PERMIT Y _____ N _____, SKIM TANK Y _____ N _____, DIMENSIONS _____ GALLONS
LEASE SIGN: YES _____ NO _____ TANK ID: YES _____ NO _____ NA _____ FENCED: YES _____ NO _____
SURFACE EQUIPMENT: _____
COMMENTS: _____

DATE OF P&A INSPECTION 6/24/87

PITS BACKFILLED: YES ☒ NO _____ SURFACE RECLAIMED: YES ☒ NO _____
HOLE MARKER: YES _____ NO ☒ SITE CLEAN: YES ☒ NO _____
BOND RELEASE OK: YES ☒ NO _____ LANDOWNER RELEASE: YES _____ NO _____

COMMENTS: 5/1/86 plugged well, dirt work to finish. (6/18/86, 7/30/86 - No change)
6/24/87 Final P&A inspection OK

DATE OF SAFETY INSPECTION _____

COMMENTS: _____

INSPECTOR SP

API No. 05-075-06651

P&A Inspected: Yes ☒ No _____