

Inspection Photos

Loc#413865

Operator: Caerus

Inspection Number: 692401655

Inspection Date: 11/19/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location from Entry. Dark spots on slope are Curly Dock Plants.

November 19, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Hilton Loc#413865



Photo#2:
Anchors.



Photo#3:
Anchors.

November 19, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Hilton Loc#413865



Photo#4:
Views of Curly Dock in Interim Reclamation areas.

November 19, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Hilton Loc#413865