

# Inspection Photos

API: 05-043-06197

Operator: PINE RIDGE OIL & GAS LLC

Inspection Date: 12/4/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019

## Inspection Photos



**Photo 1.** Facing north along the former access road. There is some gravel that remains along the road. It appears vehicles have been using the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019

## Inspection Photos



**Photo 2.** Facing north along the former access road. There is some gravel that remains along the road. It appears vehicles have been using the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019



## Inspection Photos



**Photo 3.** Facing north toward the location. There is a livestock corral placed at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019

## Inspection Photos



**Photo 4.** West side of the location facing northeast. There is vegetation establishment throughout the location which consists of Prairie threeawn, Sand dropseed, and Blue grama.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019



## Inspection Photos



**Photo 5.** Facing south at the location. There is vegetation establishment throughout the location which consists of Prairie threeawn, Sand dropseed, and Blue grama.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019



## Inspection Photos



**Photo 6.** Facing southwest at the location. There is vegetation establishment throughout the location which consists of Prairie threeawn, Sand dropseed, and Blue grama.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019



## Inspection Photos



**Photo 7.** Facing southwest at the location. There is vegetation establishment throughout the location which consists of Prairie threeawn, Sand dropseed, and Blue grama.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019



## Inspection Photos



**Photo 8.** View of ground cover at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019



## Inspection Photos



**Photo 9.** Facing east toward the surrounding undisturbed reference area which consists predominately of Blue grama grassland.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-06197 | Date: 12/4/2019