

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2019

Submitted Date:

12/09/2019

Document Number:

680305994**FIELD INSPECTION FORM**Loc ID 304938 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 66190Name of Operator: OMIMEX PETROLEUM INCAddress: 7950 JOHN T WHITE ROADCity: FORT WORTH State: TX Zip: 76120**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-854-4733	Jeremy_Fisher@omimexgroup.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276960	WELL	PR	01/01/2013	GW	125-09172	BLEDSON 8-18-3-43	PR

General Comment:

Routine Site Inspection FIR -

Location**Lease Road:**

Type	Access		
comment:	Two track grassland		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Satisfactory	Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Steel panel		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Steel panel		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Gas Scrubbers		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	@ Meter Run		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Gas engine		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	276960	Type:	WELL	API Number:	125-09172	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	GW								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for erosion management](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine FIR	schureky	12/09/2019