



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Sep 16, 2019 12:44:46 PM MDT
Server Receive Date: Sep 16, 2019 12:46:37 PM MDT
Reference Number: 20190916-18117357158
Location: 2 Co Rd 506, Bayfield, CO 81122, USA
Sep 16, 2019 12:44:12 PM MDT [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date Sep 16, 2019
Well Name MARTIN, JOE GAS UNIT 2
API Number 50670865500
Select State Colorado
Work type COGCC Inspection AR
Action Complete Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

removal of seed heads

Photo of second corrective action completed



Completed work description of corrective action 2

mullein, musk and canada thistle

Photo of third corrective action completed



Completed work description of corrective action 3

Photo of fourth corrective action completed



Completed work description of corrective action 4

Summary of all work completed

musk thistle seed head removal

removal of seed heads on thistles along road way
we removed mechanically the seed heads on musk
and canada thistle as well as some mullein on pad
site