

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #1 Wellhead & Sign

Photo #2 Production Facility

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #3 is missing placard/ Label

Photo #4 is missing placard/ Label

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #5 is missing placard/ Label

Photo #6 is missing placard/ Label

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #7 Trash



Photo #8 Missing Capacity

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #9 Trash



Photo #10 Trash

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #11 unreadable placard/ Label



Photo #12 unreadable placard/ Label

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #13 unreadable placard/ Label

Photo #14 unreadable placard/ Label