



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Sep 24, 2019 1:03:01 PM MDT
Server Receive Date:	Sep 24, 2019 1:04:54 PM MDT
Reference Number:	20190924-18118294630
Location:	557 Airpark Dr, Durango, CO 81303, USA Sep 24, 2019 1:04:12 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Sep 18, 2019
Well Name	PAYNE, EVELYN GAS UNIT C 1
API Number	50670690400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other
Photo of first corrective action completed	



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated noxious weeds in reclamation area

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed

treated noxious weeds in reclamation area



Completed work description
Completed work description of corrective action 4
Summary of all work completed

treated noxious weeds in reclamation area
treated noxious weeds in reclamation area
treated noxious weeds in reclamation area