

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Colorado Oil and Gas Conservation Commission
40.45486, -104.87382, 1425.7m, 24°
Dec 9, 2019 13:48:03

Photo 1: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.45484, -104.87383, 1425.1m, 15°
Dec 9, 2019 13:48:08

Photo 2: Wellhead

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 3: Stained soil



Photo 4: Stained soil (different angle)

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 5: Wellhead Sign



Photo 6: Wellhead

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 7: Stained soil



Photo 8: Stained soil (different angle)

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Colorado Oil and Gas Conservation Commission
40.45484, -104.87378, 1431.8m, 353°
Dec 9, 2019 13:53:44

Photo 9: Stained soil (different angle)



Colorado Oil and Gas Conservation Commission
40.45446, -104.87476, 1435.4m, 13°
Dec 9, 2019 13:56:45

Photo 10: Tank Battery Sign

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Colorado Oil and Gas Conservation Commission
40.45446, -104.87472, 1434.8m, 304°
Dec 9, 2019 13:56:55

Photo 11: Tank Battery



Colorado Oil and Gas Conservation Commission
40.45452, -104.8748, 1432.3m, 268°
Dec 9, 2019 13:57:07

Photo 12: No NFPA placard