

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 1 – Wellhead



Photo 2 – Tank Battery

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Colorado Oil and Gas Conservation Commission
40.94436, -104.17867, 5198.7ft, 76°
12/05/2019 11:05:37

Photo 3 – NFPA Label has peeled off