

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402258241

Date Received:
12/09/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

The subreport 'rtpNoav' could not be found at the specified location \\DnrDenSterling\FirmReports\FIRR\InspCont

OGCC INSPECTION SUMMARY:

FIR Document Number: 696501186

Inspection Date: 12/02/2019

FIR Submit Date: 12/02/2019

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 318592

Location Name: LOIS DINNER UNIT-64N66W Number: 13SESW County: _____

Qtrqr: SESW Sec: 13 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.308410 Longitude: -104.729310

FACILITY - API Number: 05-123-00 Facility ID: 318592

Facility Name: LOIS DINNER UNIT-64N66W Number: 13SESW

Qtrqr: SESW Sec: 13 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.308410 Longitude: -104.729310

The subreport 'rtpNoav4' could not be found at the specified location \\DnrDenSterling\FirmReports

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 12/9/2019 2:21:59 PM

The subreport 'Attach1stNew' could not be found at the specified location \\DnrDenSterling\FirmReports\New\Attach1stNew