

WRD Federal 19-21, Ant Hill Unit 19-22

API: 05-103-10041, 10231

Inspection: 679706493



40.12938, -108.21371, 6012.8ft, 240°
12/09/2019 09:47:51 AM

Photo 1. Location.

WRD Federal 19-21, Ant Hill Unit 19-22

API: 05-103-10041, 10231

Inspection: 679706493



Photo 2. Meter buildings & separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

WRD Federal 19-21, Ant Hill Unit 19-22

API: 05-103-10041, 10231

Inspection: 679706493



40.12933, -108.21415, 6004.1ft, 148°

12/09/2019 09:48:51 AM

Photo 3. Tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

WRD Federal 19-21, Ant Hill Unit 19-22

API: 05-103-10041, 10231

Inspection: 679706493



Photo 4. Tank battery.

WRD Federal 19-21, Ant Hill Unit 19-22

API: 05-103-10041, 10231

Inspection: 679706493

Leak



Photo 5. Well heads.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

WRD Federal 19-21, Ant Hill Unit 19-22
API: 05-103-10041, 10231
Inspection: 679706493

Leak



Photo 6. Leaking valve.



Photo 7. Container without label.