

Final Reclamation Inspection

December 9, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 327317

Inspection Document #: 697500890

Weld County, CO

SWSW Section 35 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO E #1
Location ID: 327317



Photo 1. Photo taken from the central point of the access road, facing East. Appears the Operator has performed additional reclamation activities in response to the previous corrective action inspection.

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO E #1
Location ID: 327317



Photo 2. Photo taken the central point of the access road, facing East. Photo illustrates that the western access road has a land use change to housing development. Operator will still be responsible for the eastern access road, well location and production facility- see Photo 5 for additional information.

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO E #1
Location ID: 327317



Photo 3. Photo taken the central point of the access road, facing South. See comments under Photo 2.

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO E #1
Location ID: 327317



Photo 4. Photo taken the central point of the access road, facing West. See comments under Photo 2.

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO E #1
Location ID: 327317



Photo 5. Aerial imagery from Weld County Property Portal illustrates that most of the access road appears to be a land use change to housing development. Operator will still be responsible for the eastern access road, well location and production facility.