

Inspection Photos
Operator: Williford Resources
Location/API #: 067-06772
Date: 11-19-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is comprised of weedy annual mustards, as well as mixed wheatgrasses.



Photo 3. View of reference area, largely comprised of s weedy annual mustards, as well as mixed wheatgrasses.