



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Nov 18, 2019 4:28:23 PM MST
Server Receive Date:	Nov 18, 2019 4:30:29 PM MST
Reference Number:	20191118-18123319373
Location:	557 Airpark Dr, Durango, CO 81303, USA Nov 18, 2019 4:27:24 PM MST [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Nov 18, 2019
Well Name	DOWNING, RALPH GAS UNIT A 2
API Number	50670849900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other

Photo of first corrective action completed



Completed work description Corrective Action 1

Sprayed musk thistle population.

Photo of second corrective action completed



Completed work description of corrective action 2

Sprayed musk thistle population.

Photo of third corrective action completed



Completed work description of corrective action 3  
Photo of fourth corrective action completed

Sprayed musk thistle populations.



Completed work description  
Completed work description of corrective action 4  
Additional photos

Sprayed musk thistle populations.  
Sprayed musk thistle populations.



Completed work description  
Summary of all work completed

Sprayed musk thistle populations in the reclamation area.  
Sprayed musk thistle populations.