

Inspection Photos
Operator: Williford Resources
Location/API #: 067-06698
Date: 11-19-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is comprised of big sagebrush, snakeweed, crested wheatgrass, and annual weeds such as yellow tumbled mustard.



Photo 3. View of stained soils at well pump-jack, need to be cleaned and properly disposed of.



Photo 4. View of reference area, largely comprised of sagebrush, mixed wheatgrasses, and annual weeds such as yellow tumbled mustard and *Allysum simplex*.