

Inspection Photos
Location Name: Dinner Lois Unit #2
Location ID: 318592



Colorado Oil And Gas Conservation Commission
40.30841, -104.72955, 1422.0m
12/10/2019 8:51:57 AM

Production facility



Colorado Oil And Gas Conservation Commission
40.3084, -104.72944, 1425.0m
12/10/2019 8:51:07 AM

Wellhead

Inspection Photos
Location Name: Dinner Lois Unit #2
Location ID: 318592



Trash on 12/2/19



Trash on 12/10/19

Inspection Photos
Location Name: Dinner Lois Unit #2
Location ID: 318592



Trash on 12/2/19



Trash on 12/10/19